

DEPTH'S STATUS AT PENANG PORT'S INSTALLATIONS - NOVEMBER 2019

No	Terminal / Channel	Berths	Maintaining Depth (m)	Declared Depth (m)
1	<i>Butterworth Wharves Cargo Terminal (BWCT)</i>	<i>W1</i>	10.0	10.0
		<i>W2</i>	10.0	10.0
		<i>W3</i>	10.0	10.0
		<i>W4</i>	9.0	9.0
		<i>W5</i>	9.0	9.0
		<i>W6</i>	9.0	9.0
		<i>VOTP</i>	8.0	8.0
2	<i>North Butterworth Container Terminal (NBCT)</i>	<i>N1</i>	11.0	11.0
		<i>N2</i>	11.0	11.0
		<i>N3</i>	11.0	11.0
		<i>N4</i>	12.0	12.0
		<i>N5</i>	12.0	12.0
		<i>N6</i>	12.0	12.0
		<i>Inner Berth</i>	7.5	7.7
3	<i>Perai Bulk Cargo Terminal (PBCT)</i>	<i>BCT1</i>	11.0	11.0
		<i>BCT2</i>	11.0	11.0
		<i>BCT3</i>	11.0	11.0
		<i>DG</i>	11.0	11.0
		<i>Inner Berth</i>	7.5	7.6
4	<i>North Channel (NC)</i>		11.0	11.0
5	<i>South Channel (SC)</i>		5.8	6.0
6	<i>Approaches to PBCT /Ferry Channel (FC)</i>		11.0	11.0
7	<i>Swettenham Pier Cruise Terminal (SPCT)</i>			
	<i>Outer Berth</i>		11.0	11.0
	<i>North Inner</i>		6.5	6.7
	<i>South Inner</i>		5.5	5.6